

Date: March 22, 2006

TECHNICAL

Subject:

Erratic Fuel Gage Readings (Does Not Go to Full or Moves Off Full Too Quickly) (Replace Fuel Level Sensor)

Models:

2006 Chevrolet Cobalt

2006 Pontiac Pursuit (Canada Only)

Built Prior to VIN Breakpoints 67735784 (Chevrolet) and 67735794 (Pontiac)

Condition

Some customers may comment on erratic fuel gage readings. A typical comment might be that the gage does not go to full or moves off full too quickly.

Cause

This condition may be caused by an improperly calibrated fuel level sensor.

Correction

Do This	Don't Do This
Replace the fuel level sensor	Do not replace the fuel pump module

Replace the fuel level sensor. Refer to the Fuel Level Sensor Replacement procedure in the service information.

Parts Information

Part Number	Description
88967308	Sensor Kit, Fuel Level

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time